


ALL WIRES DENOTED 'PL' ARE JOINED TOGETHER

DASH ACC. SWITCH PIGTAIL

DASH INSTRU. PIGTAIL



THUNDERBIRD PRODUCTS
 P.O. BOX 501
 DECATUR, IN 46733
 219-724-9111

TITLE
 FORMULA THREE LS WIRING SCHEM. (DASH)
 DR BY
 CH BY
 SCALE
 DATE
 12/27/82

 CORRECTION

DATE
 NAME

MATERIALS

DRAWING NO.
 TOLERANCES UNLESS SPECIFIED
 X.XX
 X.XXX

13195
 (TACH)

* TO FUSEBLOCK

THUNDERBIRD PRODUCTS
 P.O. BOX 501
 DECATUR, IN 46733
 219-724-9111

TITLE
 F-3 US LAYOUT WIRING DIAGRAM

DR BY	CH BY	SCALE	DATE
NHJ	JIL	7/1/84	


THUNDERBIRD PART NO. 1

ADD	DATE	NAME
ADDED 30-5971	7-12-85	DUB


MATERIALS

TOLERANCES UNLESS SPECIFIED
 X.XX
 X.XXX

DRAWING NO.



ALL WIRES DENOTED 'PL' ARE JOINED TOGETHER




THUNDERBIRD PRODUCTS
 P.O. BOX 501
 DECATUR, IN 46733
 219-724-9111

TITLE		DATE	
F-3 LS DASH WIRING DIAGRAM		7/28/83	
DR BY	CH BY	SCALE	
NML	JUL		
#		CORRECTION	
DATE		NAME	
MATERIALS		DRAWING NO.	

TOLERANCES UNLESS SPECIFIED
 X.XX
 X.XXX

DASH INSTRU. PICTAL



HUNDERBIRD PRODUCTS
 O. BOX 501
 ECATUR, IN 46733
 219-724-9111

TITLE: F-3 US DASH WIRING DIAGRAM
 DR BY: CH BY: SCALE: DATE: 2/11/84
 THUNDERBIRD PART NO.:

CORRECTION


DATE NAME

MATERIALS

DRAWING NO. TOLERANCES UNLESS SPECIFIED X.XX X.XXX

01850 7/11/84

ALL WIRES DENOTED 'PL' ARE JOINED TOGETHER




THUNDERBIRD PRODUCTS		TITLE		F-3 LS DASH WIRING DIAGRAM	
P.O. BOX 501		DR BY	CH BY	SCALE	DATE
DECATUR, IN 46733		NWL	JTL		2/1/84
219-724-9111		THUNDERBIRD PART NO.			
#	CORRECTION	DATE	NAME	MATERIALS	TOLERANCES UNLESS SPECIFIED
1	CHANGED BLOWER FUSE FROM 7.5 TO 15	1/11/83	NWL		X.XX X-XXX
					DRAWING NO.

THUNDERBIRD PART NO.

THUNDERBIRD PRODUCTS
 P.O. BOX 501
 DECATUR, IN 46733
 219-724-9111

TITLE
 F-3 US LAYOUT WIRING DIAGRAM
 DR BY CH BY SCALE DATE
 THUNDERBIRD PART NO. 7/1/84


#	CORRECTION	DATE	NAME	MATERIALS	DRAWING NO.
TOLERANCES UNLESS SPECIFIED					X-XXX
					X-XXX



* TO FUSEBLOCK

(BOB NAV LT.)
 (FRONT PORT SPKR.) W/Y (+)
 W/BA (-)
 W/BA (-)
 (CABIN LTS.)
 LBU/W
 BA
 (CABIN LT.)
 LBU/W
 BA
 (HORN) O/W
 BA
 (CABIN LT.)
 LBU/W
 BA
 (COURT. LT.) DBU/W
 BA
 (REAR PORT SPKR.) W/BR (+)
 W/BR (-)
 (TO ENGINE)
 LGN
 (FUEL) PK
 (FUEL TANK SENDER)
 R/BR
 BR
 (AUTOMATIC BILGE PUMP SWITCH)
 BR
 (BILGE HARNESS)
 R/BR
 BA
 (THUNDERBIRD REPLACEMENT)
 #30-5968
 BA
 (BATTERY) 10 AMP FUSE
 BA
 Y
 Y
 7.5 AMP FUSES
 BA
 BR
 (PUMP)
 BR
 BA

ALL WIRES DENOTED 'PL' ARE JOINED TOGETHER



DASH INSTRU. PIGTAIL

75-4200

NEUTRAL SAFETY SWITCH Y/R

FROM DECK ACC. HARNESS O/R

75-4199

THUNDERBIRD PRODUCTS
 P.O. BOX 501
 DECATUR, IN 46733
 219-724-9111


TITLE
 F-3 LS DASH WIRING DIAGRAM
 DR BY CH BY SCALE DATE
 MNL JLL
 THUNDERBIRD PART NO. 2/1/84

#	CORRECTION	DATE	NAME

MATERIALS
 DRAWING NO.
 TOLERANCES UNLESS SPECIFIED
 X.XX
 X.XXX

THUNDERBIRD PRODUCTS
 P.O. BOX 501
 DECATUR, IN 46733
 219-724-9111


TITLE		F-3 LS LAYOUT WIRING DIAGRAM	
DR BY	CH BY	SCALE	DATE
THUNDERBIRD	THUNDERBIRD		7/27/81
PART NO.		#	
CORRECTION		DATE	
		NAME	
		MATERIALS	
DRAWING NO.		TOLERANCES UNLESS SPECIFIED	
		X.XX	
		K.KXX	



7/1/89

18

ALL WIRES DENOTED 'PL' ARE JOINED TOGETHER



THUNDERBIRD PRODUCTS
 P.O. BOX 501
 DECATUR, IN 46733
 219-724-9111

TITLE	DATE
F-1 IS DASH WIRING DIAGRAM	2/1/84
DR BY CH EY	
MML JLL	

#	CORRECTION
2	ADDED ENGINE HATCH SWITCH
1	CHANGED BLOWER FUSE FROM 7.5 TO 15

DATE	NAME
7-12-83	DLB
1/11/84	NML

MATERIALS

TOLERANCES UNLESS SPECIFIED
 X.XX
 X.XXX
 DRAWING NO.